



Kirby Morgan Dive Systems, Inc.®

1430 Jason Way, Santa Maria, California 93455

Phone: 805/928-7772 Fax: 805/928-0342

www.kirbymorgan.com e-mail: kmdsi@kirbymorgan.com

Bulletin #4 of 2025. June 10, 2025

MAINTENANCE AND REPAIR BULLETIN


Port Insert Test Sheet

Products Affected: All fiberglass Kirby Morgan® helmets and both models of BandMasks®.

A2.1 Annual Inspection/Overhaul/Maintenance Checklist **MUST** include a signed and completed Port Insert Test Sheet. A2.1 Annual Inspection/Overhaul/Maintenance Checklists recorded without the Port Insert Test Sheet may be considered incomplete.

Testing of the Port Inserts should be conducted ONCE A YEAR, and/or whenever damage to the Port Insert is present or suspected, using KMDSI P/N 525-115, Thread Insert Testing Block Kit.

Guidance and the test sheet are available under the Support tab on the Kirby Morgan website in the Misc. Appendices section - [Thread Insert Testing Procedure](#).

Port Insert Test Sheet	
Test Results: P=Pass F=Fail	Date _____ Company _____
	Helmet/KMB Model _____ SN# _____
	Technician _____
1 _____	
2 _____	
3 _____	
4 _____	
5 _____	
6 _____	
7 _____	
8 _____	
9 _____	
10 _____	
11 _____	
12 _____	
13 _____	
14 _____	
15 _____	
Notes/Comments: _____	

Fiberglass repairs must be performed by an authorized KMDSI service center. For more information contact Kirby Morgan Dive Systems or Dive Lab Inc. Copyright 2016, Dive Lab Inc.

Fiberglass Helmets ONLY

The test sheet also serves as the last page of the A2.1 Annual Inspection/Overhaul/Maintenance Checklist.

Printed manuals for Kirby Morgan Dive Systems have not been produced since 2017 and can be accessed, downloaded, and printed from the Kirby Morgan® website starting that year. Always refer to the most up-to-date information by using the Kirby Morgan® website.

Please contact your authorized KMDSI dealer or e-mail sales@kirbymorgan.com for more information.

