

Kirby Morgan Dive Systems, Inc.®

1430 Jason Way, Santa Maria, California 93455 Phone: 805/928-7772 Fax: 805/928-0342 www.kirbymorgan.com e-mail: kmdsi@kirbymorgan.com

Bulletin #7 of 2015. May 26, 2015

Change to Product Effective immediately, 530-145 Locknuts no longer included with Kirby Morgan Band Mask[®] Hoods. 510-712 replaces 525-740.

Products Affected: Standard (foam face seal) Hood Assemblies w/Locknuts: 525-740. Molded Face Seal Hood Assemblies P/Ns 525-730, 525-731, 525-732, 525-733, 525-734, 525-735, 525-736, 525-737. Mask Spares Kit 18/28, 525-327.

Overseas Spares Kit 18/28, 525-319.

530-145 lock nuts have been shipping along with spare BandMask[®] hoods since January 2004. Reference bulletin, Change to Product #1 of 2004. These locknuts are no longer included. Explanation below.

The primary example of the "spare BandMask[®] Hood" most of you are familiar with is the 525-740.

P/N 510-712 is the standard hood you have been receiving when ordering P/N 525-740, and the hood that is the standard on all production $BandMasks^{\circledast}$.





525-740 (now obsolete) Hood & Face Seal with Locknuts (530-145)

510-712 Hood & Face Seal Replaces 525-740

This lock nut was used only in the very first, original model **Hood & Keeper Kit** (ref. Bulletin #4 of 2003). The original model Band Keepers became obsolete March 2004, no longer requiring the 530-145 lock nut. A much easier & efficient band keeper kit was introduced late April 2004 (ref. an "All Dealer

© MMXV Kirby Morgan Dive Systems, Inc. All Rights Reserved Document #150501003

Page 1 of **2**





Kirby Morgan Dive Systems, Inc.®

1430 Jason Way, Santa Maria, California 93455 Phone: 805/928-7772 Fax: 805/928-0342 www.kirbymorgan.com e-mail: kmdsi@kirbymorgan.com

Faxed Notice May 11, 2004). Locknuts were shipping with hoods as an **assurance that anyone still using the original keepers receive a new lock nut** (an extra was also included) for the bottom band keeper when changing the hood. The 530-145 nut is a one-time use only lock nut.

If some customers do still happen to be using the original band keepers, they may purchase replacement lock nuts.

No other part number changes. No price changes at this time.

Kirby Morgan strongly recommends the use of band keepers on all KMB 18 and 28 BandMasks[®]:

525-172 Band keepers with hood, 525-121 Band keeper Kit, No Hood.

Please contact your local KMDSI dealer or e-mail KMDSI at sales@kirbymorgan.com for more information.

