

## Kirby Morgan Dive Systems, Inc.®

1430 Jason Way, Santa Maria, California 93455 Phone: 805/928-7772 Fax: 805/928-0342 www.kirbymorgan.com e-mail: kmdsi@kirbymorgan.com


## Bulletin #6 of 2010. October 6, 2010 (UPDATED August 12, 2019) Change To Product Bulletin Length of Part Number 530-024, Screw, Increased

**Assemblies and Kits Affected:** 505-090, 505-093, 505-094, 505-095, 505-097, 505-100, 505-101, 505-102, 505-104, 505-118, 505-119, 505-120, 505-744, 505-745, 505-746, 505-747, 525-216, 525-230, 525-341, 525-347, 525-349, 525-372 and 525-379.

Kirby Morgan has slightly increased the length of part number 530-024, neck ring assembly screw, to better accommodate the various **dry suit yokes** that may have variations in thickness. This will help provide maximum thread engagement when using a lock in dry suit configuration.

The length of the screw was increased from ½" to %6". The length added to the screws was done in case needed. The additional length is not required for standard neck dams.

No change in price.



Please contact your local KMDSI dealer or e-mail KMDSI at sales@kirbymorgan.com for more information.

